ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: M121272 Alaskan Copper Works Client: Date Received: 12/04/08 Project: PO M121272, F&BI 812051 Lab ID: Date Extracted: 12/08/08 812051-01 x10 12/09/08 Date Analyzed: Data File: 812051-01 x10.037 Matrix: Water Instrument: ICPMS1

Units: hr

ug/L (ppb) Operator:

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 82 60 125

Concentration Analyte: ug/L (ppb) Chromium 635 Nickel 543 Copper 394 Zinc <20

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank Alaskan Copper Works Client: Date Received: Project: PO M121272, F&BI 812051 NA

12/08/08 Date Extracted: Lab ID: 18-460 mb 12/09/08 Data File: I8-460 mb.011 Date Analyzed: Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: hr

Lower Upper Internal Standard: Limit: % Recovery: Limit:

100 125 Germanium 60

Concentration ug/L (ppb) Analyte:

Chromium <1 Nickel <1 Copper <1 Zinc <2

ENVIRONMENTAL CHEMISTS

Date of Report: 12/10/08 Date Received: 12/04/08

Project: Metro Self Monitor, PO M121272, F&BI 812051

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 812012-01 (Duplicate)

					Relative	
		Sample	1	Ouplicate	Percent	Acceptance
Analyte	Reporting Units	Result	17.7	Result	Difference	Criteria
Chromium	ug/L (ppb)	3.24		3.45	6	0-20
Nickel	ug/L (ppb)	2.74		2.89	5	0-20
Copper	ug/L (ppb)	2.36		2.37	0	0-20
Zinc	ug/L (ppb)	4.67		3.40	31 a	0-20

Laboratory Code: 812012-01 (Matrix Spike)

Analyte	Reporting Units	Spike Level	Sample Result	Percent Recovery MS	Acceptance Criteria
Chromium	ug/L (ppb)	20	3.24	109	50-150
Nickel	ug/L (ppb)	20	2.74	100	50-150
Copper	ug/L (ppb)	20	2.36	97	50-150
Zinc	ug/L (ppb)	50	4.67	94	50-150

Laboratory Code: Laboratory Control Sample

Analyte	Reporting Units	Spike Level	Percent Recovery LCS	Acceptance Criteria		
Chromium	ug/L (ppb)	20	109	70-130		
Nickel	ug/L (ppb)	20	103	70-130		
Copper	ug/L (ppb)	20	103	70-130		
Zinc	ug/L (ppb)	50	88	70-130		

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probablility.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb The analyte indicated was found in the method blank. The result should be considered an estimate.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht The sample was extracted outside of holding time. Results should be considered estimates.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- is The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve The value reported exceeded the calibration range established for the analyte. The reported concentration should be considered an estimate.
- vo The value reported fell outside the control limits established for this analyte.
- x The pattern of peaks present is not indicative of diesel.
- y The pattern of peaks present is not indicative of motor oil.

Send Report To Genz	ers /	Hompso	2		PRS (signa				\leq	82236	149000			Т		ROUND TIME
Company ALASKAN		/ 1111		- Met	CT NAME/ 20 Seld		Ne	~;\	tor		n	170#		 ★ RUS	H_S	2 Weeks) authorized by
Address <u>628</u> City, State, ZIP Sea Phone # 206-57-6		Andered CUA # 206-			RKS				E*		<u></u>	÷ş	S	☐ Disp	SAMPL osc aft	LE DISPOSAL or 30 days
										ANA	LYS	ES REQ	UEST	ED		
Sample ID	Lab ID	late Sampled	Time Sampled	Sample Type	# of containers	TPH-Diesel	TPII-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCs by 8270	IIFS	PRCUNE ZN				Notes
2F5151M	0[12/4/08	12:30	420	1				-		1					170.00
3						Н	-	-	-	+	+	-	-		+	
									_						\perp	

Friedman & Bruya, Inc. 3012 16th Avenue West

Seattle, WA 98119-2029

Ph. (206) 285-8282	
Fax (206) 283-5044	
ORMS/COC/COC DOC	

/ SIGNATURE	PRINT NAME	COMPANY	DATE	TIME	
Relinguished of	- GREERE THOURSON	ALEXAZ CAPPER	12/4/08	2:21pm	
my and aw	19han Phan	FEBI	12/4/08	2:21	
Relinquished b:	l o		7		
Received by:		Samples received a	14 °C	ris "	

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

December 10, 2008

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 4, 2008 from the Metro Self Monitor, PO M121272, F&BI 812051 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you should have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1210R.DOC